



KVA 1500 / 1680 S/N ST0614A35469-1-1
HV 4800 BIL 60 HV/LV CONDUCTOR AL/AL
LV 480 Y 277 BIL 30 LV AMPS 1804

HIGH VOLTAGE		TAP CHANGER	
VOLTS	AMPERES	POSITION	CONNECTS
5040	171.8	A	
4920	176	B	
4800	180.4	C	
4680	185	D	
4560	189.9	E	

TYPE ONAN HZ 60
RISE 55/85 °C % IMP. 5.67
APPROX. WEIGHT IN POUNDS
UNTANKING 3900
TANK & FITTING 3314
LIQUID 1113
GAL 430 3290
TOTAL WEIGHT 11052



MFG: SUNBELT TRANSFORMER LTD.
24/7 Sales & Service
Domestic: (800) 433-3128
International: (305) 517-3657
www.sunbeltusa.com

Handwritten number: 116





SUNBELT
ELECTRICAL
2017 Sales & Service
Customer Support 1-800-543-5437
www.sunbeltusa.com

DANGER
High Voltage
Electrical Equipment
Do Not Open
Without Proper
Training
Consult with
Manufacturer

WARNING
High Voltage
Electrical Equipment
Do Not Open
Without Proper
Training
Consult with
Manufacturer

WARNING
High Voltage
Electrical Equipment
Do Not Open
Without Proper
Training
Consult with
Manufacturer

Manufacturer
Do Not Open
Without Proper
Training
Consult with
Manufacturer



UNIT 89

405459-1-1



UNIT 89





DE-ENERGIZE TRANSFORMER
BEFORE OPERATING SWITCH



CAUTION:
BUSBARS WILL NOT SUPPORT WEIGHT
OF CABLES. CABLES MUST BE SUPPORTED
BY THE INSTALLER TO PREVENT DAMAGE
TO BUSBARS.

BR
H1A



DR
H2A



Y4
H3A



H3B



H2B



H1B





OR

X1

y

X3

CAUTION:
BUSHINGS WILL NOT SUPPORT WEIGHT
OF CABLES. CABLES MUST BE SUPPORTED
BY THE INSTALLER TO PREVENT DAMAGE
TO BUSHINGS.

BR

X2

X0





